

U.S. Senate

Desk Description and Condition Report

Desk No : **66.00100.000**

Paper Label No.(on shelf bottom): N/A

Painted No. (on bottom): N/A

Other identifying labels or marks (specify location): Stretcher: "C"; Top of drawer blade: "1"; Inside edge of lid opening: "35"; Top surface of inkwell support: "1"; Drawer bottom: "Roddiscraft Quality for over 60 years"; Outside drawer back: "1"; Inside back rail: "1"

Description of Desk

Dimensions (in inches)

	Overall	Orig. Desk*	Case	Shelf
Height	35 7/8	35 7/8		
Width (front)	28	28	25 1/2	
Width (rear)	27 7/8	27 7/8	25 1/2	
Depth	20 1/4	20 1/4	19	9 7/8

* Note: Dimensions do not include the "booster" blocks added to feet or the writing top.

Woods

Primary:

Mahogany ☒

Mahogany veneer ☐

Rosewood veneer ☐

Other Wood (specify): _____

Character of case mahogany:

Plain ☒

Ribbon ☐

Mottled ☐

Crotch ☐

Other ☐

Secondary:

Element	Pine	Ash	Poplar	Mahog	Other
Drawer Sides				✓	
Drawer Bottom					plywood w/ mah. veneer
Drawer Back				✓	
Case Interior	✓			✓	
Drawer Front				✓	

Construction Details

Leg:

Wood Type	rosewood crossband	other crossband	no crossband
mahog. veneer			
solid mahogany			✓
other: _____			

Foot construction: 1-part ☒

2-part ☐

5-part ☐

Other: Block

Double bead on edge of leg:

Thickness: 1 1/4 "

Shape of cross-stretcher edges:

Rounded ☐

Rectangular ☒

Spindle type:	Thick	Thin	Other
Number	11		

Joinery of lower drawer blade to case sides:

single dovetail ☐

2 dovetails ☐

3 dovetails ☐

lap joint ☐

other: Unknown

Cockbead width on bottom of drawer front:

Narrow ☐

Full width ☒

Opening in original top for inkwell: Yes ☐

No ☐

Roundels: Single piece ("yo-yo" form) ☐

Applied boss ☒

Inset distance of single bead on desk back panel:

Side: 1 3/16"

Top: 1 3/16"

Bottom: 1"

No. of Glue Blocks	Case	Stretch'r	Shelf
Original/Old	10		
New/Recent			
Missing			

Case built-out for drawer: Yes ☐

No ☒

Condition of Desk

Structure

Previous breaks in structural elements: Yes ☐
(show on schematic)

No ☒

Current split or broken elements: Yes ☐
(show on schematic)

No ☒

Other loose or damaged joinery: Yes ☐
(describe in narrative)

No ☒

Damage to drawer fronts: Extreme ☐
Moderate ☒
Minor ☐

Drawer lock: relocated on face Yes ☐

Drawer lock: resized on inside Yes ☐

Cockbead on drawer front: Damaged ☒
(show on schematic)

Missing ☐

Loose ☐

Replacements ☐

Replaced drawer-side runners: Yes ☐

No ☒

Replaced case-side runners: Yes ☐

No ☒

Drawer bottom pieced-out at back edge: Yes ☐

No ☒

Wear on Feet	Extreme	Moderate	Minor
Front		✓	
Rear			✓

Number of loose spindles:

No: 0

Number of replaced spindles:
(show on schematic)

No: 0

Replaced veneers and cross-banding: Yes ☐
(show on schematic)

No ☒

Missing veneers and cross-banding: Yes ☐
(show on schematic)

No ☒

Delaminated/loose veneers & cross-banding: Yes ☐
(show on schematic)

No ☒

Shelf supports: Original/old ☒

New/recent ☐

Missing ☐

Shelf molding applied: Yes ☐

No ☒

Dowel support board in case: Yes ☐

No ☒

Finish

Age	Excellent	Good	Fair	Poor
New		✓		
Old				
Unk.				

Note: Describe finish problems in narrative.

Hardware/Attachments

Item	Mismatch	Missing	Damaged
Knob (L)			✓
Knob (R)			✓
Toe cap size:		Right toe: 8	
		Left toe: 8	